
## DRILLING PROBLEM NO.2



- A. The above is a full size drawing of your part dimensions can be read with a ruler.
- B. Holes must be drilled with a 1 inch drill bit.
- C. Tolerance is //6".
- D. You are responsible for all drilling operations.